

1064nm High Power 3-port PM Optical Circulator

FEATURES

- High Isolation 0
- Low Insertion Loss 0
- **Epoxy-Free Optical Path** 0
- High Reliability and Stability 0
- Low Profile Packaging 0
- WDM Systems 0 **Dispersion Compensation**

Fiber Optic Amplifiers


Fiber Optic Instruments

ÅPPLICATIONS

0

0

Light Routing 0



SPECIFICATIONS

Parameter		Unit	Value		
Center Wavelength		nm	1064		
Operating Wavelength Range		nm	+/-10		
Insertion Loss@ 23 °C (Typ.)		dB	0.8		
(1 → 2 or 2 → 3)	(Max.)	dB	1.5		
Isolation @ 23 °C	(Typ.)	dB	25		
(3 → 2 or 2 → 1)	(Min.)	dB	22		
Work Mode	S Type	-	Can only work in slow axis		
	F Туре	-	Can work both in slow axis and fast axis		
Optical Return Loss		dB	≥45		
Extinction Ratio		dB	18		
Fiber Type		-	PM980 Fiber, PM1060L Fiber (E) or PM1060L-FA Fiber (L)		
			10/125um PMDC Fiber (O), 15/130um PMDC Fiber (W)		
			20/130um PMDC Fiber (Q) or 25/250um PMDC Fiber (R)		
Fiber Tensile Load		Ν	5		
Maximum Optical Power (CW)		W	0.5, 1, 2, 3, 5, 10, 15, 20, 25, 30		
Operating Temperature		°C	0~50		
Storage Temperature		°C	-10~65		

Note: 1. Specifications are for device without connectors; Specifications may change without notice.

2. To add connectors, IL is 0.5dB higher, RL is 5dB lower, ER is 2dB Lower, Connector key is aligned to slow axis.


3. Only guarantee 1W continuous wave (CW) power thru testing for connectors added.


4. Devices for higher optical power or with other type fiber or consigned fiber are also available; Devices can only


work in the core of Double Cladding (DC) Fiber, Cladding Power must be stripped before connecting the device.


5. Package size maybe different for different fiber type, optical power, etc.

PACKAGE DIMENSION









ORDERING INFORMATION (PN)

FPCR-	NNNN	- (<mark>C</mark>) 3I	HP NN	- (NN)	- C	С	NN	- CC/CCC
	Center Wavelength	Work Mode	Optical Power	Optical Power P2	Fiber Type	Fiber Sleeve	Fiber Length	Connector Type
	<mark>1064</mark> =1064nm	F=F Type	<mark>05=</mark> 500mW	1- 1W	2-PM980Fiber	<mark>B=</mark> Bare Fiber	<mark>05=</mark> 0.5m	N=Without Connector
		<i>Blank</i> for S Type	1= 1 Watts	<mark>2-</mark> 2W	E=PM1060L Fiber	L= Loose Tube	10=1.0m	FC/APC=FC/APC Connector
			<mark>5=</mark> 5 Watts	<mark>5=</mark> 5W	Q=20/130 PMDC Fiber	<mark>2=</mark> 2mm Cable	<mark>15=</mark> 1.5m	LC/PC=LC/PC Connector
			<mark>20=</mark> 20 Watts	<i>Blank</i> for P2=P1	R=25/250 PMDC Fiber	<mark>3=</mark> 3mm Cable	<mark>20=</mark> 2.0m	SC/UPC=SC/UPC Connector
						Compliant		
🚮 htt	ps://www.l	naphit.com	🛛 🖂 sales(@haphit.com				Compliant